

Update notes for DR 306 firmware Updates

Preparations: Installation of USB driver for Firmware updates

Caution: The DR 306 is using 3 different USB interfaces with different drivers depending on the software functions!

a) For MP 3 upload the device works as mass storage flash device and does not need any driver under Windows XP.

b) for DAB mode it is possible to address the DAB module by the chipset's manufacturer's USB driver

c) for firmware updates the USB drivers of the Firmware update directory must be installed.

Firmware Update USB Driver installation

Step 1: Turn the DAB off.

Step 2: Plug in USB cable to PC and connect it to DAB.

Step 3: Hold "+" (the volume up), and then press the power switch.

Step 4: If the DAB can be detected successfully

There will pop up a dialog box for "Add new hardware device".

If not, then unplug USB cable and repeat Step 1 ~ 4.

Step 5: Choose button for "Select from menu or specific location"

Press "Next" button.

(not "automatical detect !")

Step 6: Select "Do not search, I will choose by myself" button.

Press "Next" button.

(not "Search from location")

Step 7: Press "Install from diskette" button

Press "Browse" button.

Step 8: Select "**usbio_ti.inf**"

Step 9: Press "Next" button Complete.

Firmware Upgrade procedure

1. unzip the firmware file if still necessary
2. run the file "***DabUpbApp_Man.exe***"
3. connect the DAB with PC by USB cable
3. ***hold the (+) button***, and then ***press power for about 3 seconds***
5. there will be a text "[USB_01]" on the right-top frame
6. click "browse" and choose the file "***Dabman_B_1.pro***"
7. click "***Download product***"
8. it will start to upgrade and take 7 minutes to complete